

The Thermoclick fix key bracket must be positioned on the purlin and be pushed against the panel and located in the groove.